

© 2015 Mazda Motor of America, Inc.

Subject: REAR CONSOLE LID DOES NOT LATCH (BROKEN LATCH)	Bulletin No: 09-012/15
	Last Issued: 04/17/2015


APPLICABLE MODEL(S)/VINS

2014-2015 Mazda3 (Japan built) vehicles with VINS lower than JM1BM*****227327 (produced before August 1, 2014)

2014-2015 Mazda3 (Mexico built) vehicles with VINS lower than 3MZBM*****157427 (produced before October 6, 2014)

DESCRIPTION

Some vehicles may exhibit the rear console lid (A) not being able to latch due to a broken latch (B).



The latch may be broken by excessive external force applied to the lid. To correct the problem, the rear console lid latch has been changed to increase the strength.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify customer concern.
2. Replace the rear console lid assembly with a modified one according to the instructions on MS3 online or the Workshop Manual (section 09-10 REAR CONSOLE DISASSEMBLY/ASSEMBLY).
3. Verify repair.

PART(S) INFORMATION

Part Number	Description	Qty.
BHN1-64-450B02	Rear Console Lid, PVC	1
BHN2-64-450C02	Rear Console Lid, Vinyl Leather	1

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	42 (Does not lock)
Damage Code	9A (Broken)
Part Number Main Cause	****-64-450***
Quantity	1
Operation Number / Labor Hours:	XXL38XRX / 0.2 Hrs.